CONFIDENTIAL

			چانوين	. wina				
			CENTI	RAL INTELLIGE	NCE AGENCY			25X1A
			INFO	RMATION	REPORT			
COUNT	RY	USSR				REPORT N		
SUBJE	СТ	Novorossisk - Security/Cond	Port Con	ditions/Aids Piers/Ships	to Navigation/	RESPONSI	VE TO	25X1A
	ACQUIRED		7	· · · · · · · · · · · · · · · · · · ·		CD NO. 00/C NO.		-
	ACQUIRED			٦		DAS NO.		
	OURCE)					OCI NO.		25X1A
DATE	(OF INFO					DATE DISTR.	8 Nov 19	
•		THIS DOCUMENT CONTAINS I OF THE UNITED STATES, WI AND 794. OF THE U.S. COD	THIN THE MEANING	OF TITLE 18. SECTIONS	3 782 1EVE-	NO. OF PAGES		
		LATION OF ITS CONTENTS T Prohibited by Law. The R		AN UNAUTHORIZED PERSO This report is prohibi				
25X1		THIS IS UNE	VALUATED	INFORMATION		SUPP. TO REPORT NO.		•
1. 25X1	by US When app 1954 at ceeded in pilot be with him The navi Point (1) were rep 37°48.7°	Naval Hydrographoroaching Novo a position apposition and two guatant two guatant and two guatant light of the second seco	aphic Of rossisk to proximate no position ards account at Doob 52.9'E), no perations of the continuous continu	fice he ship was l ly 1.2 miles n 44°42.5'N, mpanied the passe Point (44°3' and the light on. The light		ot ob Point and protection of Point and protection of Point and protection of Middle Grown), the range at 9.7'N, 37049.6 aya Kosa (4404)	ro- as a board nd". t Pensi 'E, 0.3'N,	25X1 25X1 25X1 25X1 25X1
25X1	Wrecks.	ut 400 yards 1	wrecks, e	of the coali	o a small portioning pier. There			
25X1	No Gun Eapproach	mplacements No to the harbon	oted.	no ge in port.	oun emplacements	ide of pier #3		
OI	This car the grai	go could have n "trimmers" werence to our a	been load were used	ded in less t	full cargo of grant in were it not assengers ships	for the fact	that	25X1
	mpleted.	~,			v			20/(1
			(CONFIDENTIAL				25X1A کن د
DISTRIBU			NAVY	AIR	FBI			$\bigcup_{i=1}^{n} \omega_i$
	TENTOTES III	uicaleu above. It	18 not to	ne transmitted	gence components of overseas without the fice of Collection an		44	7

		Approved For Release 2003/10/0 2 : CIA-RDP80-00926 A007500400007-0 CONFIDENTIAL	25X1A 25X1
		-2-	
4	3.	Condition of Piers.	
25X1		Cement Pier. not observe any activity on this pier. However, the cement works, which are located inland from the cement pier, were extremely active and work was in progress both night and day.	
25X1		Coaling (Inport) Pier. no activity on this pier except that it was used as a berth for two naval minesweepers entering the	25X1
	•	port.	25/(1
	• .	Passenger Pier. This pier which shows been demolished and no longer exists.	25X1
25X1		Oil Pier. Approximately 135 yards of the former pier extending out from the shore is still in existence. no activity on this pier.	
	•	Piers #1, #2 and #4. These three piers have not been rebuilt.	
		Pier #3 (elevator pier). passenger vessels arriving are moored on the northeast side of this pier. The	25X1
		grain elevators on the pier are in fair condition, no use was being made of the railroad tracks. The snip was loaded by chutes;	25X1
	3	no cranes were in evidence. Fresh and boiler water are reportedly available at this pier. Cost and quantity were undetermined.	
		Pier #5. This pier is very active. Oil is piped to the pier from a tank	
25X1		farm about half a mile inland. two Italian and two Finnish cargo vessels loading fuel oil at this pier. several oil barges being towed by tugs which appeared to be in good condition. These barges were	25X1
		brought alongside the oil pier, loaded there and towed away again to unknown destinations.	
25X1	. •	Coasting Mole. no activity on the coasting mole.	***
	4.	Ships Observed. Passenger Ships. Other than some small coastal passenger ships, which tied up	
		on the northeast side of the elevator pier (pier #3), the Soviet vessel "ROSSIA". She appeared to be heavily loaded with passengers.	25X1 25X1
	-	informed that this vessel was in service between Novorossisk, Batum and Poti.	20/(1
		Cargo Vessels. Mention has already been made of the two Italian and two Finnish cargo vessels which were loading fuel oil at pier #5.	25X1
25X1		a Turkish vessel, which was ex-German. she was about 25 years old. finished loading and moved	25X1 25X1 25X1
	** 1	out, she moved into the same berth and commenced loading grain.	23/1
		Naval Vessels. The only naval vessels were the two naval minesweepers which were mentioned above as berthing at the coaling pier.	25X1
25X1 25X1	5.	Security. was searched both on arrival and departure by a squad of seven or eight men. While at anchor two security boats patrolled	
25X1		around the ship. at the pier a total of three guards armed with pistols were on duty one stationed at the bow, one amidship and one aft.	
		Everyone going ashore even if it was only to read the ship's draft had	
		to have a pass issued by the gangway guard. Passports had to be carried for identification at all times.	,
25X1		General. several voyages to Novorossisk over the last few years	
25X1		d any changes to port installations. It does not seem that the port has either improved or declined in the last few years.	
25X1		During this last stay the port seemed relatively quite active. Headquarters	
		of the Agent (Inflot) are located between pier #1 and pier #2. The Harbor	
		CONFIDENTIAL	25X1

CONFIDENTIAL

		Approved For Release 2003/10/02 : CIA-RDP80-00926A007500400007-0	25X1A
		CONFIDENTIAL -3-	25X1
٠.		Master's office is located about 300 yards inland between piers #2 and #	25X1
25X1	7.	Clearing Port. After loading, the ship was anchored in the inner harbor. had to stay at anchor there for two days while the necessary ship's paper were completed and signed. After arriving got a 1954.	*s
		Anna in Wash a cross opening to Mivil Remogning to Ordice Comme NO has the opening to any and the comme no has the constraint of the const	100
		-end-	
			25X1
			,

CONFIDENTIAL

25X1